

Message

From: Jardine, Rick [Jardine.Richard@epa.gov]
Sent: 3/31/2014 1:00:14 AM
To: Hill, Franklin [Hill.Franklin@epa.gov]
Subject: Re: US Pipe NBham

Will do.

From: Hill, Franklin
Sent: Sunday, March 30, 2014 1:25:32 PM
To: Jardine, Rick
Subject: FW: US Pipe NBham

Follow up with ADEM on piles

From: Davis, Phil [mailto:PDD@adem.state.al.us]
Sent: Tuesday, March 25, 2014 10:12 PM
To: Hill, Franklin
Subject: Fwd: US Pipe NBham

FYI.

Phil

Sent from my iPhone

Begin forwarded message:

From: "Crockett, Chip" <VHC@adem.state.al.us>
Date: March 25, 2014, 7:46:45 PM CDT
To: "Davis, Phil" <PDD@adem.state.al.us>
Subject: Fwd: US Pipe NBham

See Clays write up below.

Sent from my iPhone

Begin forwarded message:

From: "Messer, Richard C" <rcmesser@adem.state.al.us>
Date: March 25, 2014 at 5:30:23 PM CDT
To: "Crockett, Chip" <VHC@adem.state.al.us>
Cc: "Espy, Brian C" <BEspy@adem.state.al.us>
Subject: RE: US Pipe NBham

Chip,

First, there should be absolutely no excavation into the landfill itself or inside the footprint of the landfill. Most likely there is some confusion as to where this "excavation" is occurring. It is my assumption that Franklin is referring to the removal of the "piles" of dirt in question a few weeks ago. I will forward you the correspondence between USPNB and myself.

Second, there should be no excavation work currently ongoing with regard to the 3 pipes without an ADEM representative on site. Also, the 3 pipes do not extend under the LF.

Third, I just spoke to David Lovoy who was at the site performing an O&M last Thursday, 3/20/14. He assured me that no excavation has occurred recently in the area of the 3 pipes (scalping basin) or the LF itself. David indicated that there did appear to be some work/moving dirt/excavation occurring on the north side of the LF, where the "piles" in question are.

Ultimately, upon the Department's questioning of these "piles" on site, north of the LF, USPNB supplied justification and reasoning as to what the "piles" originated from. Instead of digging up records that would indicate the piles were characterized as non-hazardous, USPNB agreed to re-sample the piles for characterization and remove them from the site accordingly. The piles were sampled on 3/13/14 with the anticipated results in about 10 days. I have not received any analytical yet from USPNB, but will contact them to find out what work, if any, is going on at the site.

Also, look for the correspondence emails mentioned earlier in this message. I will forward them to you shortly after I send this email. Let me know if you have any other questions.

Thanks,
Clay

From: Crockett, Chip
Sent: Tuesday, March 25, 2014 4:50 PM
To: Messer, Richard C
Cc: Espy, Brian C
Subject: FW: US Pipe NBham

Clay:

Have you been to the site recently? Can you provide any insight as to what this excavation might be?

Chip

-----Original Message-----

From: Davis, Phil
Sent: Tuesday, March 25, 2014 4:12 PM
To: Crockett, Chip
Subject: US Pipe NBham

Franklin asked me about the excavation occurring at the USPNB landfill. He said it looked "bad" from the street and needed attention. He asked about excavation into the cap and the removal of foundry sand. I told him that we had work occurring under the RCRA permit concerning a pipe that runs under the LF but that I didn't have the details in front of me but that your folks had been to the site recently.

Anything more you want me to tell him?

Sent from my iPhone